



LEGEND


- PROPERTY LINE
- APPROXIMATE LIMIT OF REFUSE
- UNDERGROUND ELECTRIC (TO BE ABANDONED)
- FENCE LINE
- EXISTING CONTOUR 10'
- EXISTING CONTOUR 2'
- MW-205 NEW MONITORING WELL LOCATION
- G-124 MONITORING WELL LOCATION
- P-125 LIQUID PROBE LOCATION
- EWL-1 LEACHATE EXTRACTION WELL
- MH-1 LEACHATE COLLECTION SYSTEM MANHOLE
- DV-12 DEEP GAS VENT
- SV-1 SHALLOW GAS VENT
- B-4 SOIL BORING - AUGUST 14, 1996
- TP-24 TEST PIT LOCATION - SEPTEMBER 5, 1996
- ST-12 SOIL TEST LOCATION - MAY 15, 2002
- + BENCHMARK
- * UTILITY POLE
- X 816.5 SPOT ELEVATION

⊗ Potential Monitoring probes (Gas)

NOTE:

1. EXISTING TOPOGRAPHY PROVIDED BY MARTINEZ CORP., MENDOTA HEIGHTS, MN, DATED 8/22/99
2. THE LIMIT OF REFUSE DEPICTED ALONG THE NORTHWEST, NORTH, EAST, AND SOUTHEASTERN LANDFILL PERIMETER IS APPROXIMATED BASED UPON INFORMATION FROM SOIL BORINGS AND TEST PITS. THE LIMIT OF REFUSE ALONG THE REMAINING LANDFILL PERIMETER IS ESTIMATED FROM BORINGS, TOPOGRAPHY, MH-1, AND MH-2. SOME WASTE MAY EXIST BEYOND THE ESTIMATED LIMITS SHOWN.
3. THE 100-YEAR FLOODPLAIN INFORMATION WAS OBTAINED FROM A 1994 RUST ENVIRONMENT AND INFRASTRUCTURE REPORT ENTITLED "MALLARD NORTH LANDFILL SITE CHARACTERIZATION".
4. THE SITE BENCHMARK IS THE NORTHEAST CORNER OF THE TOP SPAN OF THE BRIDGE OVER THE WEST BRANCH DUPAGE RIVER. THE SURVEY INFORMATION WAS PROVIDED BY THE FOREST PRESERVE DISTRICT OF DUPAGE COUNTY.

FINAL COVER DESIGN APPLICATION



REV	DATE	DESCRIPTION	OWN BY	DES BY	CHK BY	APP BY
1	11/8/2002		ISS	MAC	PPV	DSV

FOREST PRESERVE DISTRICT OF DUPAGE CO.
MALLARD NORTH LANDFILL
HANOVER PARK, ILLINOIS

EXISTING SITE CONDITIONS

DRAWING NO.

1